

New Rear Deck Lift Pin

Subject: A new modified Rear Deck Lift Pin is now available.

Units Affected: All WSR/WSES with original lift system.

Situation: Replacement pin can be used instead of replacing entire lift system. WMI recommends these pins for all out of warranty units.

The Fix: Remove old lift pin, bolt new pin in place, drill 1 hole and bolt.

P/N's Affected: 93460054 will include 1ea. DL Pin, 2ea. 11990012 bolts and 2ea. 12990007 nuts.

