

## Defective 3" Fuel Cap

**Subject:** Defective 3" fuel caps for EPA/CARB compliant tanks

**Units**

**Affected:** All units with the new EPA/Carb compliant fuel tanks

**Situation:** Wright received 170 defective 3" fuel caps from our vendor. (See below photo for defective cap) The defective cap does not tighten properly and may allow a small amount of fuel to leak.


**The Fix:** Inspect unit(s) for current cap. Replace defective cap if necessary. The below photo illustrates both the defective cap and the proper cap. Replacement caps can be ordered thru your distributor. (PN45410002)

**Claim**

**Procedure:** File normal on-line warranty claim, .2 hr allowed per unit. Type 45410002 as part failed and for part replaced. Return defective caps back to your distributor using the WMI UPS account. (Ref Bull 83C) Distributors are to return caps to WMI when batches of ten or more are received.



**Defective Cap** – Has fuel pump and text "Unleaded Gasoline Only" on dome



**Good Cap** – Has smooth dome with zero diagram or text