



Bulletin # 067
Page 1 of 1
March 20, 2008

Drive Belt Lower Tension Idler Kit

- Subject:** Drive belt breaks under extreme conditions
- Units Affected:** All Small Standers, WSES and WSR
- Situation:** Field issues raised concerns over the tension of these drives. Belts would break when unit is operated in tight areas requiring a lot of turning.
- The Fix:** A field service Idler kit (P/N 95490005) has been created to lower the belt tension of the engine to pump drive belt. Replace drive belt (71460033, not included in kit) along with the Idler Kit.
- Claim Procedure:** 1.0 hours allowed if work performed within the normal warranty period of the mower.
File normal warranty claim referencing Bulletin # 67.