

New Spindle

Subject: Replacement spindle for 71460092 and 71460057

Units

Affected: WZ and WSE s/n 39286 and below, WSR and WSES s/n 43612 and below.


Situation: The 71460092 Spindle shaft was failing prematurely. A new spindle has been developed.

The Fix:

A new spindle has been developed (71460114). If a unit is brought in for service in regards to spindles and has 71460092 spindles installed, (Identified in figure below) **all** spindles will be replaced (regardless of failure).

NOTE: This only applies to the 7140092 spindles.

- If a unit is brought in for spindle service and 71460057 spindles are installed then only replace the bad spindle (**DO NOT REPLACE ALL SPINDLES**)
- All 71460092 spindle inventory should be discarded. Contact your Distributor with new in stock quantities (if applicable) for credit.
- All inventories of 71460057 spindles are to be depleted.
- Units out of warranty with 71460092 spindles will be covered for parts only for an additional year. Distributors must email WMI Service Department for an authorization number.



Claim

Procedure: File normal warranty claim