



Service Bulletin # 097  
Page 1 of 1  
June 24, 2010

## 71410014 Clutch Wire Tie Location

**Subject:** Revised wire tie procedure for the 71410014 clutch

**Units**

**Affected:** Small frame Stander, Sentar Sport, Stander RH, and Velke mowers.

**Situation:** Possibility for the clutch wires to break when the clutch wire was only wire tied to the clutch stop.

**The Fix:** Using an existing hole in the clutch bell housing the clutch wire will be wire tied to the hole to keep the wire stationary at the clutch during the operation of the clutch.

**Claim**

**Procedure:** Informational only / internal assembly revision



Location for Wire Tie



Wire tie prior to installing