



Sentar Spindle Kit

One-belt cutter decks, PN95460021

Subject: Replacement spindle kit for early Sentar's.

Units

Affected: Any early Sentar mower with the one belt cutter deck needing spindle replacement.

Situation: New spindle (71460114) can cause interference with the deck covers.

The Fix: Install new Spindle kit to lower spindle in the cutter deck. Order PN95460021

Claim

Procedure: None, unless still under warranty.

Sentar Spindle Kit / One Belt Cutter Deck		
PN 95460021		
PN	Description	Qty
11990090	BOLT, HCS, 1/4-20X1 PLAIN	2
11990132	BOLT, FLANGE 3/8-16 X 1 1/2 Z5	4
12990008	NUT, LOCK FLANGE 3/8-16 Z	4
13990011	WASHER, FLAT USS 5/8 Z	1
15990003	MACHINE KEY 1/4 X 1/4 X 1	1
71460111	BUSHING, SPLIT TAPERED 1' MODIFIED	1
71460114	SPINDLE, ASSEMBLY	1
93460117	SPINDLE SPACER, 3/8"	1

- Spindle and Spacer are installed from under the cutter deck

