



Parts Bulletin # 008P  
Page 1 of 1  
June 24, 2010

## Eliminate 32410006 CCW Wheel Motor

**Subject:** In our continual effort to keep lean and improve our processes, WMI has eliminated p/n 32410006 CCW wheel motor to now use p/n 32410005 CW wheel motor for both sides of the drive system.

### Units

**Affected:** All ZK's, WSE's and MMZ's, S/N 49228 and below.

**Situation:** To keep stock levels down, WMI will start using one wheel motor to run both sides. Hydro Gear has approved the system.

**The Fix:** Install CW wheel motor and reverse HP hoses at WM fittings.

### Claim

**Procedure:** File a normal warranty claim. 1.0 hours of labor is allowed.

### Shipped with wheel motor if 32410006 is ordered;

32410006 wheel motor is OBSOLETE.  
Use 32410005 for both left and right applications. PRE Serial # 49228, 32410006 was used on the left side. When using a 32410005 in place of the 32410006 (pre serial # 49228) you must first reverse the hose connections