



Bulletin # 063

2 Pages




October 5, 2006

Pulley

Parts information

- Subject** The 71460069 pulley is being replaced with a new pulley
- Units Affected:** Stander 42" – serial 26288 through 35903
Sentar 52" & 61" – serial 26988 through 35988
Z 52" & 61" – serial 30200 through 36009
- Situation:** Pulley 71460069 is being replaced with part number 71460098. 71460098 requires a bore adapter and additional hardware for proper installation, fit and function
- Part number 71460069 is being superseded by kit part number 71460106 (for Sentar and Z applications). When an order is received for 71460069, it will be filled with 71460106. 71460106 is a kit that includes:
- 71460098 – pulley
 - 22420007 – bore adapter for certain Sentar and Z mowers
 - 13990038 - washer
- ➔ If replacing the pulley on a 42" Stander, see below for individual component part numbers – a pulley kit is not available for this mower
- Additional parts information is listed below.
- The Fix:** This is not a recall - use the information provided to order the correct parts only as needed
- Claim Procedure:** None – this is for informational purposes only

This information applies to mower models that currently are using the 71460069 pulley



1		Nut, 3/8 – 16	12990031
2	*	Washer, Flat 3/8x1-1/2	13990038
3	*	Idler Pulley 6"	71460098
4	*	Bore Adaptor WSE, WZ	22420007
5		Bolt, 3/8 – 16 x 2-1/4	11990068
6	*	Bore Adaptor WS 42	22420006
7	*	Bolt, 3/8 – 16 x 2-3/4	11990006

Items with an asterisk (*) are required for the initial upgrade to the 71460098 pulley.