



Bulletin # 070
Page 1 of 1
April 16, 2008

Hydro Gear BDP 10L 117P Pumps

Subject: WMI will no longer carry the **BDP 10L 117P** (31490001 and 31490003) pumps

Units

Affected: Standers (Small, S/N 20303 and below), (Large, S/N 20425 and below) All Standers under the serial range listed use 31490001.

Sentars (S/N 19729 and below) All Sentars under the range listed use 31490003, which is a 31490001 with shock valves installed.

Situation: Due to minimal orders and a steep price increase from our vendor, we will no longer offer the 10L hydro pumps from Hydro Gear.

The Fix: Pumps can be purchased direct from HG. The link below is Hydro Gear North American Service Dealers.
<http://www.hydro-gear.com/Support/NorthAmerica.aspx>

It is highly recommended when replacing the pumps on Sentars to install shock valves in these pumps. WMI will still offer the shock valve kits (P/N 31490002). When replacing either the Stander or Sentar pump order **BDP 10L 117P**.

Claim

Procedure: None, informational only.
All open back orders will be canceled.