

New Hydro Tanks & Vented Hydro Caps

Subject: Removal of hydro tank vent tube and adding vented hydro caps (P/N 36410006)

Units

Affected: Hydro Velke mowers, ranging from S/N 43191 and greater
Small Standers, ranging from S/N 43206 and greater
Sentar Sport and RH Stander, ranging from S/N 43186 and greater

Situation: Manufacturing and Product Improvement. Previous hydro tanks had a vent tube which was difficult to weld. WMI has eliminated the need for the vent tube with the use of the improved hydro tank and vented cap. Under certain conditions the vent tube allowed hydro oil to leak from these tanks. The new tank eliminates the vent tube and replaces the solid hydro cap with a vented cap.

The Fix: N/A. Improved tanks, informational only

Claim

Procedure: N/A

Old (35410015)



New (36410006)

