



Service Bulletin # 095
Page 1 of 2
Feb. 22 2010

New Spindle For Large Frame Standers

Subject: Replacement spindle for 71460007

Units

Affected: All Large frame Standers prior to serial number 49705

Situation: 71460007 spindles will no longer be available for replacement and are being replaced with 71460126 spindles.

The Fix: Kit number 95460016 has been created and includes the new spindle and necessary hardware and parts needed to install the new spindle. All inventories of 71460007 spindles are to be depleted. Only failed 71460007 spindles are to be replaced with the spindle kit. Units out of warranty will not be covered. See below for parts list and installation diagram.

Claim

Procedure: File normal warranty claim. 0.5 hr of labor is allowed for each spindle. Reference kit # 95460016 on the warranty claim instead of 71460007.



SPINDLE KIT 95460016 PARTS LIST

95460016 KIT CONTENTS		
PN	DESCRIPTION	QTY.
11990132	BOLT FLANGE LOCK, 3/8-16 x 1 1/2 Z5	4
12990008	NUT, FLANGE LOCK, 3/8-16 Z5	4
13990011	WASHER, FLAT, 5/8 Z5	1
71460126	SPINDLE, ASSEMBLY STANDER	1
93460117	SPINDLE SPACER	1

